



Sedgwick County...
working for you

FACTS & details

about Sedgwick County Government

October 2009

INTRUST Bank Arena Fan Experience - Spectator Facilities

	<u>Units</u>	<u>SF</u>	<u>Total SF</u>
Seating			
Armchair Seating (20")	7,200	7.00	50,400
Armchair Seating (19")	7,000	6.65	46,550
Club Seating (21-22")	300	7.70	2,310
Suite Seating (22")	308	0	0
Loge Seating (21-22")	192	40	7,680
Barstool Seating in Suites	96		
Subtotal:			106,940
Seating Bowl			
Private Suites	10	450	4,500
Future Suites	12	450	5,400
Party Suite	2	700	1,400
Subtotal:			11,300
Loge Boxes			
32 boxes w/4 seats, 8 boxes w/8 seats 40		(counted above)	(counted above)
Club Lounge/Hospitality			
Club Lounge	250	12	3,000
(Located behind club seats, includes bar and bar seating, some standing tables)			
End Zone Club	150	25	3,750
(Restaurant at end zone w/view out of floor)			
Suite Lounge	1	900	900
Pre-function/Party Room	1	1,500	1,500
Subtotal:			9,150
Public Restrooms			
Men's – Public Toilets	121	55	6,655
(1:300 toilet; 1:90 urinal; 1:200 lavatories)			
Women's – Public Toilets	139	55	7,645
(1:60 toilet; 1:150 lavatories)			
Men's – Suite Level Toilet Rooms	4	300	1,200
Women's – Suite Level Toilet Rooms	4	300	1,200
Family Toilets	7	70	490
Subtotal:			17,190
Spectator Support			
First Aid Room	1	500	500
Fan Assistance Booth	1	(SF counted w/concourse)	
Subtotal:			500
Total Estimated Square Feet:			145,080