



SEDGWICK COUNTY, KANSAS

DIVISION OF FINANCE

Purchasing Department

525 N. Main, Suite 823 Wichita, KS 67203

Telephone (316) 660-7255

Fax (316) 383-7055

**REQUEST FOR PROPOSAL
08-0306
LAUNDRY EQUIPMENT
SEDGWICK COUNTY DOWNTOWN ARENA**

ADDENDUM #1

November 07, 2008

The following are question(s) received in reference to RFP # 08-0306, Laundry Equipment for Sedgwick County Downtown Arena. Questions are in *italics* and answers are in **bold** text.

Please acknowledge receipt of this addendum on the Proposal Response Form in the appropriate place.

- 1. Under item 4. Minimum Requirements and Specifications you state that the specifications are based on a UniMac Model 55 Gas Dryer (this is a 55 lbs capacity dryer), but listed under equipment specifications the capacity is listed as 75 lbs. Which is correct?* **It should have read that it was based on a Unimac Model F75.**
- 2. Under the specifications for the gas dryer is listed a water inlet size of 3/4". This connection is only provided on dryers with the C.A.R.E. System (Combustion Auto Response Equipped- Fire suppression system). Should the dryer be quoted with this option?* **It has been determined that the Fire Suppression System should not be listed as a minimum specification. However, it can be quoted as an option. All responses will be evaluated; more than one response can be submitted.**
- 3. Would it be possible to do a site inspection of the area the equipment would be installed at?* **The site is still under construction and not available for site visits.**
- 4. In regards to the voltage of both the Washer/Extractor and the Dryer, both are listed as 208 voltage. Is that single phase or three phase?* **The circuit for both the washer and dryer are - fused 30 amp, 3 phase, 240 volts.**
- 5. Would you please supply the information on where the laundry equipment will be, if it is on the ground floor or upper floor? Also, could you send this in autocad or pdf?* **Attached is sheet A1-1, Service Level Plan (ground floor). The laundry room is located in the northwest quadrant, column R19, Room No. 01-R19-E1.**

6. *On 4A is minimum of one (1) year warranty on parts or parts and service?* **Parts and Service.**
7. *On 4B is the steam inlet connection necessary?* **It has been determined that the Steam Inlet Connection should not be listed as a minimum specification. However, it can be quoted as an option. All responses will be evaluated; more than one response can be submitted.**

Kandace Johnson

Kandace Johnson, CPPB
Senior Purchasing Agent